



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program January 21, 2010

Reviewed:

Mine Name: Crown Asphalt Ridge	Permit Number: M/047/0032
Operator Name: Crown Asphalt Ridge	Inspection Date: November 18, 2009
Inspector(s): L Heppler	Time: 3:00 pm
Other Participants: KTIA	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 03-15-2014 **Bond Amount:** \$302,000 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was last inspected as a Large mine site on 11/01/2006

Inspection Summary: The Mine operation includes a mine pit (w/highwall) and an on-site process facility. Several large ponds, stockpiles and administration offices are also on-site. Large stockpiles of asphalt are stored on site. No stockpiles of topsoil were noted on site. Every effort should be made to salvage top soil and stockpile enough topsoil on site for future reclamation.

Photos were taken to document site conditions and are attached.


Conclusions and Recommendations: Permit NOI should be updated to reflect disturbance on site. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature


LAH:vs

Cc: Tom Bactell


O:\M047-Uintah\M0470032-Crown-AsphaltRidge\inspections\Insp-11182009.doc



Facilities



Storage Tanks



Mine Area



Mine Area